

CORNER RECORD

DPD-3011 (Rev. 9/97) CT# 7541-4548-0

Document Number 1N26-16-5

City of _____

County of MONO, California

Brief Legal Description PROPERTY CORNERS: SECTION 16/17 T1N R26E M.D

SEC	SEC
17	16

CORNER TYPE

Government Corner Control
 Meander Property
 Rancho Other
 Date of Survey JULY 7, 1998

COORDINATES (Optional)

N. SEE SKETCH ON
 E. PAGE 2 OF 2
 Zone 3 NAD27 NAD83
 NAD83 Epoch 1986
 Elevation _____
 Vert. Datum: NGVD29 NAVD88
 Meas. Units: Metric Imperial

C.G.F. = 0.99961137

Corner - Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:
FOUND TWO REBARS WITH ALUM. CAPS STAMPED "LS 5149"
SEE PAGE 2 OF 2 FOR DETAILS.

A description of the physical condition of the monument as found and as set or reset: _____

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on JULY 7, 1998.

Signed Brian L. Jared P.L.S. or R.C.E. Number 6620
 For the State of California
 Department of Transportation



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received 7-13, 98 and examined and filed 7-22, 98.




Signed John Kendall Beck P.L.S. or R.C.E. Number 665, 3884
 Title DEPUTY MONO COUNTY SURVEYOR EXP. 6-30-00

County Surveyor's Comment _____





PT#303: FND. REBAR w/ALUM.
 CAP STAMPED "LS 5149", FLUSH,
 ON STEEP SIDESLOPE 16m WEST
 OF C/L MNO 395 @ PM 51.11
 N = 662,124.194
 E = 2,121,438.930



C/L MNO 395

PT#302: FND. REBAR w/ALUM. CAP
 STAMPED "LS 5149", 0.03m UP,
 w/2" ODIP, NO TAG, UP ~~0.07m~~ 0.23m,
 0.07m SE OF REBAR. PP# 4100723E
 IS 20m NORTH OF REBAR.
 P.P.# 1995758E IS 25.1m NW OF
 REBAR.
 N = 662,034.586
 E = 2,121,352.864

