


# CORNER RECORD

Document Number 2N26-7-9

City of \_\_\_\_\_ County of MODO, California

Brief Legal Description LOT 9, BLOCK 5 MODOCITY SUBDV. NO 2, SEC 7, T2N, R26E, N03E1/4



### CORNER TYPE

Government Corner  Control   
 Meander  Property   
 Rancho  Other   
 Date of Survey 5-14-96

### COORDINATES (Optional)

N. \_\_\_\_\_  
 E. \_\_\_\_\_  
 Zone \_\_\_\_\_ Datum \_\_\_\_\_  
 Elev. \_\_\_\_\_

Corner — Left as found  Found and tagged  Established  Reestablished  Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

FIND REMAINS OF REDWOOD HUBS ORIG. PER MR 7/29 AT NW, NE & SE OF LOT 9, BLKS 5. ALSO FIND REDWOOD HUBS @ BCR OF LOT 10 ON HELEN COURT. THESE HUBS HAD 3/8" REBAR ADJACENT TO THEM. DIRECT REPLACED ALL REDWOOD HUBS WITH 3/8" REBAR & CAPS "LS 4587". HELD HUBS ON HELEN COURT FOR LINE ON FRONT OF LOT 9 & REC. BEARING FROM END SE. TO ESTABLISH THE SW OF LOT 9

A description of the physical condition of the monument as found and as set or reset: SET 3/8" REBAR CAP "LS 4587" @ NW, NE, SE & SW CORNERS OF LOT 9. ALSO SET SAME @ BCR OF LOT 10 ON HELEN COURT

### SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on \_\_\_\_\_ 19\_\_\_\_.

Signed [Signature] L.S. or R.C.E. Number 4587



### COUNTY SURVEYOR'S STATEMENT


This Corner Record was received 2-14 <sup>2000</sup> and examined 18 and filed 3-15 <sup>2000</sup>.

Signed [Signature] Title DEPUTY MUNDO COUNTY SURVEYOR  
EXP. 6-30-00



County Surveyor's Comment \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_

SCALE:  
1"=50'



LEGEND

- FND 2X2 ORIG PER MB 7/29A ROTTED, REPLACED WITH 5/8" REBAR & CAP STAMPED "LS 4587"
- SET 5/8" REBAR & CAP STAMPED "LS 4587"
- R1 RECORD INFORMATION PER MB 7/29A

BASIS OF BEARING

THE NORTH LINE OF LOT 9 PER MB 7/29A BETWEEN FND. 2X2 REDWOOD HUBS AND SHOWN HEREON AS N 89°38'00" W

LOT 12

