

**CORNER RECORD**


4S 29-26-3

Document Number \_\_\_\_\_

City of \_\_\_\_\_

County of MONO, California

Brief Legal Description SECTION 26, T4S, R29E MDM



**CORNER TYPE**

Government Corner  Control   
Meander  Property   
Rancho  Other   
Date of Survey 9/20/02

**COORDINATES (Optional)**

N. \_\_\_\_\_  
E. \_\_\_\_\_  
Zone \_\_\_\_\_ NAD27  NAD83   
NAD83 Epoch \_\_\_\_\_  
Elev. \_\_\_\_\_  
Vert. Datum: NGVD29  NAVD88   
Meas. Units: Metric  Imperial

Corner - Left as found  Found and tagged  Established  Reestablished  Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

FOUND SPIKE WAINER STAMPED "654587" ON CENTERLINE OF SOUTH LANDING ROAD AND SOUTH 1/16 LINE OF SECTION 26 SHOWN AS SET PER PM13 3/43

A description of the physical condition of the monument as found and as set or reset: THE ABOVE MENTIONED MONUMENT WAS DESTROYED BY ROAD CONSTRUCTION. IT WAS DIRECT REPLACED FROM SURVEY TIES WITH A BRASS DISC PUNCHED & STAMPED "654587" SET IN CONCRETE INSIDE A MONUMENT WELL

**SURVEYOR'S STATEMENT**

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyor's Act on 6/17/04

Signed [Signature] P.L.S. or R.C.E. No. 4587



**COUNTY SURVEYOR'S STATEMENT**

This Corner Record was received 04-14-2005

and examined and filed 07-18-2005

Signed [Signature] P.L.S. or R.C.E. No. 5050

Title Monro County Surveyor



County Surveyor's Comment \_\_\_\_\_

5/16 526

C

C

SET BRASS DISC  
STAMPED "LS4587"  
IN MON WELL

SE 1/16 526

SOUTH LANDING ROAD  
&

