


CORNER RECORD

Document Number 4529-35-13

City of _____ County of MONROE, California

Brief Legal Description LOT 30 LAKEVIEW SUBDV. SEC 35, T54S, R29E MDBEM



CORNER TYPE

Government Corner Control
 Meander Property
 Rancho Other
 Date of Survey 11-7-96

COORDINATES (Optional)

N. _____
 E. _____
 Zone _____ Datum _____
 Elev. _____

Corner — Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

END CUT SPK & TIN ORIG. & MON'S PER MB 6134 A & B EC @ LOT 26 & B C @ LOT 31 USED TO SET FRONT CORN LOT 30. & MON'S @ EACH END OF ASPEN TERRACE & FNT OF TRACT LINE USED TO PROPORTION BACK LINE OF LOT 30. FND 2X2 WITH NO TAG @ NE COR LOT 30, FEEL 0.21' INTO R/W NOT ACCEPTED

A description of the physical condition of the monument as found and as set or reset: SET 5/8" REBAR

& CAP "LS 4587" @ ALL CORNERS OF LOT 30

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on Jan 24 1997.

Signed [Signature] L.S. or R.C.E. Number 4587




COUNTY SURVEYOR'S STATEMENT

This Corner Record was received JAN. 31 2000 and examined and filed MARCH 21 2000

Signed John K Beck Title DEPUTY MONROE COUNTY SURVEYOR
LIC. EXP. 6-30-00



County Surveyor's Comment _____



SCALE:
1"=50'



LEGEND

◆ FOUND SPIKE & TIN, ORIG. C/L MONUMENT PER MB 6/34

■ FND 2X2 NO TAG, N 0'18" E 0.21' NOT ACCEPTED

○ SET 5/8" REBAR & CAP STAMPED "LS 4587"

R RECORD INFORMATION PER MB 6/34

BASIS OF BEARING

THE CENTER LINE OF ASPEN TERRACE BETWEEN FND MONS. SHOWN HEREON AS N 50°38'00"W, PER MAP BOOK 6 PAGE 34A

TRAD ENGINEERING CORP., SUITE 107, LANSING, MICHIGAN

CR3/1280-1CR