CODE NUMBER 3S - 27 - 27 - 01

# CORNER RECORD

COUNTY OF Mono T. 3S R. 27 E MDBM MERIDIAN CALIFORNIA

CORNER TYPE: GOV'T. CORNER ☐ MEANDER ☐ RANCHO ☐ CONTROL ☐ OTHER ☐

CORNER IDENTIFICATION — DATE OF VISIT 6/17/ 19 75

CORNER — LEFT AS FOUND ☐ FOUND AND TAGGED ☐ REESTABLISHED OBLITERATED CORNER ☐ REBUILT ☐

PHYSICAL DESCRIPTION OF CORNER FOUND; EVIDENCE AND METHOD USED TO IDENTIFY OR REESTABLISH

Corner was Replaced Based on the field ties to the found Corner as described on R/S map filed M.B. No. 2 Pge 50 on 3/3/60 (" Nail in rock 2' west of fence @ ground level @ Innsbruck Lodge along Forest Trail Rd. - 10-4-71 CA. Div. Hwy Same Desc. by CA. Div. Hwys. 6/26/69 — Find TRAVERSE Points USED WHEN TIE WAS MADE IN 1971 & RE-SET COR. BASED OF FIELD ANGLE & CHAINS DISTANCE

PHYSICAL DESCRIPTION OF MONUMENTS REBUILT OR PERPETUATED

Re-placed 2" I.D.I.P. w/ California Division of Highways Brass Cap Brazed & stamped as shown below. Cap is flush ± w/the ground in the 4 course used Brick planter 1' above the paved parking for Innsbruck Lodge 19' west of Board fence & 0' west of 5/8" steel pin 1½' above ground at the edge of a glob of Conc. for fence post. (B.T. Ans 3 5" for the 2" 30.)

CALIFORNIA COORDINATE SYSTEM ORDER: FIRST ☐ SECOND ☐ THIRD ☐

STATIONS USED: NGS (USC & GS) ☐ STATE ☐ COUNTY ☐ OTHER ☐ STATION _____ STATION _____

ZONE _____ ELEVATION _____ NORTHINGS (Y) _____ EASTINGS (X) _____

SKETCH: (Include reference tie or witness points, remarks and topo of area)




**SURVEYOR'S CERTIFICATE**

THIS CORNER RECORD WAS PREPARED BY ME OR UNDER MY DIRECTION IN CONFORMANCE WITH THE LAND SURVEYORS ACT ON 6/17 19 75.

SIGNED: [illegible]

L.S. or R.C.E. No. _____

**COUNTY SURVEYOR'S CERTIFICATE**

THE CORNER RECORD WAS RECEIVED _____ 19____

AND EXAMINED AND FILED _____ 19____

BY: _____

TITLE: _____

DOCUMENT No. 3S 27-27-1

STATEMENT ON BACK OF SHEET

RECEIVED COPY 5-27-81 R.C.B.

KC Pub. Wks #GR (9-74)