


CORNER RECORD

DPD-3011 (NEW 11/93)

Document Number 1N26-16-11

City of _____ County of MONO, California

Brief Legal Description PROPERTY CORNER IN SECTION 16., T. 1 N., R 26 E., M.D.M.



CORNER TYPE

Government Corner Control
Meander Property
Rancho Other
Date of Survey 4-18-00

Coordinates (Optional)

N. 661650.580
E. 2122400.492
Zone 3 NAD: '27 '83 ✓
NAD-83 Epoch (1986)
Elevation _____

Corner — Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:


* SEE CALTRANS RIGHT-OF-WAY MAP
MND-395-50.58/81.394 PAGE 13
FOR MORE INFORMATION

A description of the physical condition of the monument as found and as set or reset: FOUND REBAR
WITH PLASTIC CAP "LS 4587" FLUSH.

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on 4-18-00 49.

Signed Karl A. Riesen L.S. or R.C.E. Number 7285
For the State of California
Department of Transportation




COUNTY SURVEYOR'S STATEMENT

This Corner Record was received MAY 1, 2000 and examined and filed MAY 5, 2000

Signed John M. Beck Title DEPUTY MONO COUNTY SURVEYOR
EXP. 6-30-00




County Surveyor's Comment _____



SET 3/4" X 30" REBAR WITH
 "CALTRANS" ALUM CAP, UP ~~83~~
 0.03M, STAMPED; ~~#38+80~~
 "1238+55.668 34.586 R
 2000." WITH CARSONITE
 WITNESS POST
 1.0M TOWARD ϕ .
 N 661758.179
 E 2122325.806

ALL COORDINATES SHOWN ARE
 NAD 83 (1986) ZONE 3 METRIC
 CGF = 0.99961137



FOUND REBAR WITH PLASTIC
 CAP, "LS 4587" FLUSH.
 SET CARSONITE WITNESS POSTS
 1.0M TOWARD ϕ S.B. &
 1.0M TOWARD N.B.P.G. POINT
 SHOULD SURVIVE CONSTRUCTION
 AND BE IN MEDIAN AREA.
 N 661650.580
 E 2122400.492

NEW R/W

OLD R/W

NEW R/W