

CORNER RECORD

DPD-3011 (Rev. 9/97) CT# 7541-4548-0

Document Number 1N26-16-3

City of _____

County of MONO, California

Brief Legal Description PROPERTY CORNER; SECTION 16, T1N, R26E, MD



CORNER TYPE

Government Corner Control
Meander Property
Rancho Other
Date of Survey July 7, 1998

COORDINATES (Optional)

N. 661,524.614
E. 2,122,452.800
Zone 3 NAD27 NAD83
NAD83 Epoch 1986
Elevation _____
Vert. Datum: NGVD29 NAVD88
Meas. Units: Metric Imperial

C.G.F. 0.99961137

Corner - Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:
FOUND REBAR w/PLASTIC CAP "LS 4587", FLUSH, 14.9m
WEST OF C/L MNO 395 @ PM 50.27, w/METAL FENCE
POST 0.1m SOUTH.

A description of the physical condition of the monument as found and as set or reset: _____

SURVEYOR'S STATEMENT


This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on Brian L. Jared July 7, 1998
Signed Brian L. Jared P.L.S. or R.C.E. Number 6620
For the State of California
Department of Transportation




COUNTY SURVEYOR'S STATEMENT

This Corner Record was received 7-13 98 and examined
and filed 7-22 98
Signed John Kendall Beck P.L.S. or R.C.E. Number 2,53884
Title DEPUTY MONO COUNTY SURVEYOR EXP: 6-30-00
County Surveyor's Comment _____





PT# 319 =
FND. REBAR W/ PLASTIC
CAP, STAMPED AS
SHOWN, FLUSH W/ GROUND



TO
LEE VENDING

PM 50.27

TO
BISHOP