

CORNER RECORD

DPD-3011 (Rev. 9/97) CT# 7541-4548-0

Document Number 1N26-17-2

City of _____

County of MONO, California

Brief Legal Description SE-18, T1N, R26E, MDB & M



CORNER TYPE

COORDINATES (Optional)

Government Corner Control
 Meander Property
 Rancho Other
 Date of Survey 7/22/04

N. _____
 E. _____
 Zone _____ NAD27 NAD83
 NAD83 Epoch _____
 Elevation _____
 Vert. Datum: NGVD29 NAVD88
 Meas. Units: Metric Imperial

Corner - Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

FOUND 2 1/4" OD IP W/RCE TAG # 15557, UP 1.5 FT., CONCRETED IN ROCK MOUND W/METAL FENCE POST 2 FT EAST, 65" NORTH OF C/L MNO 120 @ POST MILE 9.99. REMAINS OF OLD WOOD STAKE ARE LYING NEXT TO PIPE.

A description of the physical condition of the monument as found and as set or reset: _____

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on JULY 22, 2004.

Signed Brian L. Jared P.L.S. or R.C.E. Number 6620
 For the State of California
 Department of Transportation




COUNTY SURVEYOR'S STATEMENT

This Corner Record was received AUG, 2004 and examined and filed 12-08-04.

Signed R. Beardman P.L.S. or R.C.E. Number 4686
 Title County Surveyor



County Surveyor's Comment _____




PM
9.99

To
TIOGA PASS

C/L MND 120

To
MND 395



FOUND 2 1/4" ODIP w/RCE
TAG# 15557, UP 1.5 FT,
CONCRETED IN ROCK
MOUND, w/METAL FENCE
POST 2 FT. EAST.
REMAINS OF OLD WOOD
STAKE LYING NEXT TO
PIPE.