


CORNER RECORD

COUNTY OF MONO T. 2 S. R. 26 E SEC. 22 M.D. MERIDIAN CALIFORNIA

CORNER TYPE: GOV'T. CORNER MEANDER RANCHO CONTROL OTHER

CORNER IDENTIFICATION - DATE OF VISIT 6-19 1986



N.E. CORNER LOT 9
 N.W. CORNER LOT 9
 S.E. CORNER LOT 9, BLOCK 15, SILVER LAKE PINES #2
 PER M.B. 1/8

CORNER - LEFT AS FOUND FOUND AND TAGGED REESTABLISHED OBLITERATED CORNER REBUILT

PHYSICAL DESCRIPTION OF CORNER FOUND: EVIDENCE AND METHOD USED TO IDENTIFY OR REESTABLISH

FD. 1" I.P. TAGGED E.C.E. 10467 @ S.W. COR. LOT 9 AND @ S.W. COR. LOT 8, SET S.E. COR. LOT 9 RECORDED ANGLE AND DIST. FROM THEM. SET N.W. COR. LOT 9 RECORDED ANGLE AND DIST. FROM FD. S.W. COR. LOT 9, SEARCHED @ N.E. COR. LOT 9, FD. OLD 2" X 2" HUB DIRECT REPLACED WITH 2" I.P. TAGGED L.S. 4587

PHYSICAL DESCRIPTION OF MONUMENTS REBUILT OR PERPETUATED


SET 2" I.P. TAGGED L.S. 4587 @ N.E., N.W., S.E. CORNER LOT 9, BLOCK 15, S.L.P. #2

CALIFORNIA COORDINATE SYSTEM ORDER: FIRST SECOND THIRD

STATIONS USED: NGS (USC & GS) STATE COUNTY OTHER STATION _____ STATION _____

ZONE _____ ELEVATION _____ NORTHINGS (Y) _____ EASTINGS (X) _____

SKETCH: (Include reference tie or witness points, remarks and topo of area)



SURVEYOR'S CERTIFICATE

THIS CORNER RECORD WAS PREPARED BY ME OR UNDER MY DIRECTION IN CONFORMANCE WITH THE LAND SURVEYORS ACT ON _____

SIGNED: _____

(L.S.) or R.C.E. No.: 4587

SEAL

COUNTY SURVEYOR'S CERTIFICATE

THIS CORNER RECORD WAS RECEIVED July 10 1986 AND EXAMINED AND FILED July 29 1986

BY: _____

TITLE: _____

DOCUMENT No. 2526-22-1

STATEMENT ON BACK OF SHEET

YES NO

