CORNER RECORD

Document Number 3527-33-34

City of Mammoth Lakes County of Mono, California

Brief Legal Description Lot 6 Mammoth Slopes Unit #4 per MB 5, Pg 111, Sec 33, T3S, R27E, MDM.



CORNER TYPE

Government Corner ☐ Control ☐
Meander ☐ Property ☒
Rancho ☐ Other ☐
Date of Survey _____

COORDINATES *(Optional)*

N. _____
E. _____
Zone _____ Datum _____
Elev. _____

Corner — Left as found ☐ Found and tagged ☐ Established ☐ Reestablished ☒ Rebuilt ☐

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner: Reset 2 pts on ℄ Lakeview from ties, established ℄ Mammoth Slopes Drive at record angle (90°) from Lakeview. Set S.E. Cors at record dist. from ℄. Set NE. cor at record dist. n'ly from ℄ int. and w'ly from ℄. Set SW and NW cors at prop. dist on line with NE and SE cors Lot 2 as fd. per Cor Rec No. 3527-33-27.

A description of the physical condition of the monument as found and as set or reset: P.K. nails & washers set at locations of RR spikes destroyed by construction at ℄ int Mammoth Slopes Drive & Lakeview, and at Lakeview & B.C. to west. Set 5/8" rebar & cap stamped "LS4587" at lot corners

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on May 27 1991.

Signed [signature] L.S. or R.C.E. Number 4587

SEAL

COUNTY SURVEYOR'S STATEMENT

This Corner Record was received 4-15 1993 and examined and filed 4-15 1993.

Signed R. Bauman Title County Surveyor
Exp. 9-30-95

LICENSED LAND SURVEYOR RICHARD C. BOURGEON SEAL No. 4686 STATE OF CALIFORNIA

County Surveyor's Comment _____

3527-33-34



LEGEND

- ● Fd. rebar & cap L.S. 4587 unless otherwise noted per corned record 3927-33-27
- ⊙ Set rebar & cap L.S. 4587 unless otherwise noted

R_1 Record Information per MB 5 page 111

R_2 Record Information per MB 10 page 7

JN 903