


CORNER RECORD

Document Number 3527-34-92

City of MAMMOTH LAKES

County of MONO, California

Brief Legal Description CENTERLINE MONUMENT, MAMMOTH VISTA NO. 2, 534, T.35, R.27E, M.D.B. & M.



CORNER TYPE

Government Corner Control
Meander Property
Rancho Other
Date of Survey 8-13-98

**COORDINATES
(Optional)**

N. _____
E. _____
Zone _____ Datum _____
Elev. _____

Corner — Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

FND ORIG. RAILROAD SPIKE PER MR 8/9 @ THE EC SOUTHEASTERLY OF THE INTERSECTION OF
MERIDIAN & MATTHEW PINES DRIVE

A description of the physical condition of the monument as found and as set or reset: SET 2" PK 1/2 WASHER

"LS 4587" AS A DIRECT REPLACEMENT OF FND RR SPIKE @ THE EC SOUTHEASTERLY OF THE
INTERSECTION OF MERIDIAN & MATTHEW PINES DRIVE DESTROYED DURING ROAD CONSTRUCTION

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on January 21 1999.

Signed [Signature] L.S. or R.C.E. Number 4587




COUNTY SURVEYOR'S STATEMENT

This Corner Record was received 1-25 1999 and examined and filed 1-29 1999.

Signed John K Beck Title DEPUTY MONO COUNTY SURVEYOR
LIC. EXP. 6-30-00



County Surveyor's Comment _____



(R) Record data per MB 8/9

DIRECT REPLACEMENT OF
 FINE RR SPIKE PER MB 8/9
 DESTROYED DURING ROAD CONSTRUCTION
 WITH 2" PK $\frac{1}{2}$ " WASHER "LS 4587"