


CORNER RECORD

Document Number 3527-34-95

City of MAMMOTH LAKES

County of MONO, California

Brief Legal Description CENTERLINE MONUMENT, MAMMOTH VISTA NO. 2, S34, T3S, R. 27E MDBEM



CORNER TYPE

- Government Corner
- Meander
- Rancho
- Date of Survey 2-13-95
- Control
- Property
- Other

COORDINATES (Optional)

N. _____
 E. _____
 Zone _____ Datum _____
 Elev. _____

Corner — Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

END ORIG RAILROAD SPIKE PER MB 8/9 @ THE POINT OF REVERSE CURVE SOUTH OF LOT 24 AND WEST OF THE INTERSECTION OF VALLEY VISTA DRIVE & MAJESTIC PINES DRIVE

A description of the physical condition of the monument as found and as set or reset: SET 2" PK & WASHER "LS4587"

AS A DIRECT REPLACEMENT OF RR SPIKE @ THE POINT OF REVERSE CURVE SOUTH OF LOT 24 AND WEST OF THE INTERSECTION OF VALLEY VISTA DRIVE & MAJESTIC PINES DR. DESTROYED DURING ROAD CONSTRUCTION

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with

the Land Surveyors' Act on January 21 1999

Signed [Signature] L.S. or R.C.E. Number 4587



COUNTY SURVEYOR'S STATEMENT


This Corner Record was received 1-25 1999 and examined

and filed 1-29 1999.


Signed [Signature] Title DEPUTY MONO COUNTY SURVEYOR LIC. EXP. 6-30-00



County Surveyor's Comment _____



NO SCALE
(B) Record data per
MB 8/9



MB 8/9

LOT 24

DIRECT REPLACEMENT OF
AND RR SPIKE PER MB 8/9
DESTROYED DURING ROAD
CONSTRUCTION WITH 2" DK
WASHER "LS 4587"

JW 1260