


CORNER RECORD

Document Number 3527-34-97

City of MAMMOTH LAKES

County of MONO, California

Brief Legal Description CENTERLINE MONUMENT, MAMMOTH VISTA NO. 3, S34, T3S, R.27E MDBEM



CORNER TYPE

Government Corner  Control   
Meander  Property   
Rancho  Other   
Date of Survey 8-13-98

COORDINATES  
(Optional)

N. \_\_\_\_\_  
E. \_\_\_\_\_  
Zone \_\_\_\_\_ Datum \_\_\_\_\_  
Elev. \_\_\_\_\_

Corner — Left as found  Found and tagged  Established  Reestablished  Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

END 2" IRON PIPE PER MB 9/33 @ THE POINT OF REVERSE CURVE NORTHEAST OF LOT 45. TIED OUT.

A description of the physical condition of the monument as found and as set or reset: SET 2" PK WASHER

"LS 4587" AS A DIRECT REPLACEMENT OF 2" IRON PIPE END PER MB 9/33 @ THE POINT OF REVERSE CURVE NORTHEAST OF LOT 45. DESTROYED DURING ROAD CONSTRUCTION

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on January 21 1999.

Signed [Signature] L.S. or R.C.E. Number 4587



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received 1-25 1999 and examined and filed 1-29 1999.

Signed John K Beck Title DEPUTY MONO COUNTY SURVEYOR  
LIC. EXP. 6-30-00




County Surveyor's Comment \_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_



NO SCALE

(P) Record data per MB 9/33



DIRECT REPLACEMENT OF FND  
2" IP RCE 15160 PER MB 9/33  
DESTROYED DURING ROAD CONSTRUCTION,  
WITH 2" PK WASHER "LS45B7"

JW 12/00