

CORNER RECORD

DPD-3011 (Rev. 9/97) CT# 7541-4548-0

SR 1209-0024

5S37-26-02

300

Document Number

City of _____

County of MONO, California

Brief Legal Description HW-25, T55, R37E, MD



CORNER TYPE

Government Corner Control
Meander Property
Rancho Other
Date of Survey 9/20/12

COORDINATES (Optional)

N. 2013105.40
E. 2322647.77
Zone 3 NAD27 NAD83
NAD83 Epoch 1991.35
Elevation 5044.23
Vert. Datum: NGVD29 NAVD88
Meas. Units: Metric Imperial

Corner - Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:
FOUND 5/8" REBAR WITH LS TAG 7002, UP 0.4' IN 3' DIA. X 1.5' HIGH ROCK MOUND WITH GREEN METAL FENCE POST 0.4' EAST. REBAR IS 1' WEST OF FENCE CORNER. SET MON. POST + PADDLE 1.0' WEST

A description of the physical condition of the monument as found and as set or reset: _____

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with

the Land Surveyors' Act on 9/20, 2012

Signed Brian L. Jared P.L.S. or R.C.E. Number 6620
For the State of California
Department of Transportation



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received FEBRUARY 10, 2014 and examined

and filed FEBRUARY 28, 2014.

Signed Brett K. Jefferson P.L.S. or R.C.E. Number 6267

Title MONO COUNTY SURVEYOR

County Surveyor's Comment _____



FOUND 5/8" REBAR w/LS TAG 7002,
 UP 0.4' IN 3' DIA. X 1.5' HIGH ROCK
 MOUND WITH GREEN METAL FENCE POST
 0.4' EAST. REBAR IS 1' WEST OF FENCE
 CORNER. SET MON. POST AND PADDLE
 1.0' WEST.

