

CORNER RECORD

DPD-3011 (Rev. 9/97) CT# 7541-4548-0

148

6N23-10-01

Document Number

City of _____

County of MONO, California

Brief Legal Description W-10, T6N, R23E, MDB+M



CORNER TYPE

Government Corner Control
Meander Property
Rancho Other
Date of Survey MARCH 26, 2008

COORDINATES (Optional)

N. 2,326,854.56
E. 6,863,191.11
Zone 3 NAD27 NAD83
NAD83 Epoch 1991.35
Elevation _____
Vert. Datum: NGVD29 NAVD88
Meas. Units: Metric Imperial

Corner - Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

Found 1 1/4" ODIP w/RCE TAG # 27104, UPO.1' IN ROCK MOUND, ON N'LY SLOPE OF DRY GULCH 30' ± UPHILL FROM BOTTOM, 15' E'LY OF B/W FENCE W/RED METAL FENCE POST 3' W'LY.

A description of the physical condition of the monument as found and as set or reset: _____

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on 3/26/08

Signed Brian L. Jared P.L.S. or R.C.E. Number 6620
For the State of California
Department of Transportation



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received Sept. 16, 2008 and examined and filed Oct. 2, 2008

Signed John S. Harris P.L.S. or ~~R.C.E.~~ Number 5050

Title Monro County Surveyor
County Surveyor's Comment _____



